

## EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	224264	(disk adj drive) hdd hdsd hds hda hdda (hard near2 drive)	US-PGPUB; USPAT	OR	ON	2006/11/08 07:21
L2	5125	L1 and (gimble flexure)	US-PGPUB; USPAT	OR	ON	2006/11/08 07:21
L3	175	L1 and (gimble flexure)	US-PGPUB; USPAT	OR	ON	2006/11/08 07:21
L4	5140	2 3	US-PGPUB; USPAT	OR	ON	2006/11/08 07:21
L5	349810	((sens\$4 detect\$4) near10 (accel\$ vibrat\$ strain pressure)) pzt\$1 piezo\$	US-PGPUB; USPAT	OR	ON	2006/11/08 07:22
L6	5105	4 and "5"	US-PGPUB; USPAT	OR	ON	2006/11/08 07:22
L7	4277	(load adj beam) loadbeam	US-PGPUB; USPAT	OR	ON	2006/11/08 07:23
L8	5125	L1 and (gimble flexure)	US-PGPUB; USPAT	OR	ON	2006/11/08 07:23
L9	1879	L7 and L8	US-PGPUB; USPAT	OR	ON	2006/11/08 07:23
L10	1865	6 and 9	US-PGPUB; USPAT	OR	ON	2006/11/08 07:23
L11	200	laminat\$4 near3 (gimble flexure)	US-PGPUB; USPAT	OR	ON	2006/11/08 07:23
L12	85	10 and 11	US-PGPUB; USPAT	OR	ON	2006/11/08 07:25
L13	84975	(disk adj drive) hdd hdsd hds hda hdda (hard near2 drive)	EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/11/08 07:24
L14	369147	((sens\$4 detect\$4) near10 (accel\$ vibrat\$ strain pressure)) pzt\$1 piezo\$	EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/11/08 07:24
L15	2175	(load adj beam) loadbeam	EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/11/08 07:24
L16	13056	(gimble flexure)	EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/11/08 07:24
L17	11	L13 and L14 and L15 and L16	EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/11/08 07:24